



8 total
 ● = PLACE FERRITE BEADS ON WIRES

DRAWING # B710 11/27/91
 MICROTUBE 200 PSU LOADING CHART

